

**Subject:** IHSB Voluntary Cleanup Checklist - North Terminal - 201-125

**From:** "Jeff Becken" <jeff.becken@catlinusa.com>

**Date:** Thu, 15 Nov 2007 06:57:38 -0500

**To:** <ginny.henderson@ncmail.net>

**CC:** "Page, Elizabeth" <Elizabeth.Page@kochind.com>, "Stephan Tyler" <steve.tyler@catlinusa.com>

Ginny,

This email is in regard to the Voluntary Cleanup Checklist submitted to you on October 19, 2007 for the Invista S.à.r.l., North Terminal – Paraxylene Facility. As of the submittal on October 19, 2007 not all of the persons listed in the IHSB “Guidelines for Assessment and Cleanup” Appendix C Sensitive Environment Contacts had responded to our inquiries. As of this email, we have received responses from 6 of the contacts. We are still awaiting a response from 17 of the contacts. We will continue to pursue a response from the remaining Agencies and will update you within the next 30 days of the progress.

If you should have any questions or comments, please feel free to contact us at 910-452-5861.

Thanks,

Jeff

[Jeffery K. Becken, P.E.](#)

CATLIN Engineers and Scientists

P.O. Box 10279

Wilmington, North Carolina 28404-0279

(Tel) 910.452.5861

(Fax) 910.452.7563

(e-mail) [jeff.becken@catlinusa.com](mailto:jeff.becken@catlinusa.com)